

08. lipanj 2022

Zapisnik

Ovim zapisnikom otpisuje se pumpa za mješanje mase u fermentatorima markr Jung SP 6. Do kvara je došlo lomom pogonske osovine i zgloba usljed upadanja metalnog dijela u pumpu. Zbog visoke cijene popravka (1347,60 eura) pumpu se ne isplati servisirati.

Uprilogu se nalazi kopija ponude popravka proizvođača pumpe.

Silvio Benčina

WILD POAR DISTILLERY I.d.o.o.
41233 Modčenić, Bona Tomić Bobić 20
018-206958939

Dear Mr. Benclna,

thank you for your request.

With pleasure we offer you:

Pos		Art.				
1	rotor shaft	7782	1	344,00 €	344,00 €	
2	universal joint	6838	1	74,00 €	74,00 €	
3	socket	8292/8294	4	20,00 €	80,00 €	
4	intermediate shaft	11233	1	392,00 €	392,00 €	
5	packing gland	7200	1	33,60 €	33,60 €	
6	sleeve	8957	2	21,00 €	42,00 €	
7	sleeve band	6841	4	5,60 €	22,40 €	
8	stator	1608	1	240,00 €	240,00 €	
9	Working time		2	59,80 €	119,60 €	
						1.347,60 €

It is possible that we need pos 2 and 3 two times.

For repairing the pump, we need the motor connecting shaft (8377) and the intermediate shield (8380).

You will then receive the fully assembled "rotating unit" back.