


1



2



3



4



5




6



7




8



9



10

14:34 pet. 7. tra 

## Diagnostic Trouble Code

System Scan - System Scan - 1 / Umetak kontrolne ploče

00779 Osjetnik vanjske temperature

Opis

### Report Information

Report Type	
Pre-Repair	
Vehicle Information	
VW	317834 miles
WVGZZZ7LZ8D078516	License #:
Report Info	
VW_WVGZZZ7LZ8D078516_DTC_202304071434 31	
Notes:	